

Side Panel Assembly Instructions


1. Screw lower bracket to side panel
2. Screw "Z" bracket to underside of the table top
3. Hook the lower bracket into the cut out in the end panel
4. Screw side panel to the "Z" bracket



#14 X 3/4" SCREW (QTY 16)



"Z" BRACKET (QTY 1)



LOWER BRACKET (QTY 1)


COMPUTER COMFORTS INC.
367 COLUMBIA
MEMORIAL PKWY.
KEMAH,TX 77565
281-535-2288

PROPRIETARY AND CONFIDENTIAL

THE INFORMATION CONTAINED IN THIS DRAWING IS THE SOLE PROPERTY OF COMPUTER COMFORTS INC. ANY REPRODUCTION IN PART OR AS A WHOLE WITHOUT THE WRITTEN PERMISSION OF COMPUTER COMFORTS INC. IS PROHIBITED.

DRAWN BY SAB	DIMENSIONS ARE IN INCHES	PART DESCRIPTION SIDE PANEL ASSEMBLY INSTRUCTIONS
DATE 5/15/20		PART#
DO NOT SCALE DRAWING		

G:\NCSW\CCI\G2 TABLES 2016\



COMPUTER COMFORTS INC.
367 COLUMBIA
MEMORIAL PKWY.
KEMAH,TX 77565
281-535-2288

PROPRIETARY AND CONFIDENTIAL

THE INFORMATION CONTAINED IN THIS DRAWING IS THE SOLE PROPERTY OF COMPUTER COMFORTS INC. ANY REPRODUCTION IN PART OR AS A WHOLE WITHOUT THE WRITTEN PERMISSION OF COMPUTER COMFORTS INC. IS PROHIBITED.

DRAWN BY SAB

DATE 5/15/20

DO NOT SCALE DRAWING

DIMENSIONS ARE IN INCHES

PART DESCRIPTION
SIDE PANEL ASSEMBLY
INSTRUCTIONS

PART#

G:\NCSW\CCI\G3-2020\